This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

PCN Title:	AD7292 Datasheet Register Address Update
Publication Date:	22-Jul-2014
Effectivity Date:	22-Jul-2014 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

AD7292 data sheet Configuration Sub-Register Addresses order correction:

Rev0 data sheet configuration sub-register addresses(incorrect)
0x13 VIN ALERT0 routing
0x14 VIN ALERT1 routing
0x15 VIN filter
0x16 Conversion delay control

Rev A data sheet configuration sub-register addresses(correct)
0x13 VIN filter
0x14 Conversion delay control
0x15 VIN ALERT0 routing
0x16 VIN ALERT1 routing

Reason For Change

Updating datasheet to correctly represent register addresses.

Impact of the change (positive or negative) on fit, form, function & reliability

There is no change in the product design or operation of the device therefore there will be no impact on the fit, form, function and reliability of the device.

Summary of Supporting Information

The correct configuration sub-register addresses are documented in Rev A of the data sheet.

Supporting Documents   None

For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative					
Americas:	PCN_Americas@analog.com	**Europe:**	PCN_Europe@analog.com	**Japan:**	PCN_Japan@analog.com
				Rest of Asia:	PCN_ROA@analog.com

Appendix A - Affected ADI Models				
Added Parts On This Revision - Product Family / Model Number (2)				
AD7292 / AD7292BCPZ	AD7292 / AD7292BCPZ-RL			

Appendix B - Revision History			
Rev	**Publish Date**	**Effectivity Date**	**Rev Description**
Rev. -	22-Jul-2014	22-Jul-2014	Initial Release

Analog Devices, Inc.