

PCN Number:	20180607000	PCN Date:	June 10, 2018
Title:	Datasheet for TLV707, TLV707P		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**TEXAS
INSTRUMENTS**

TLV707, TLV707P

SBVS153F – FEBRUARY 2011 – REVISED MAY 2018

Changes from Revision E (February 2016) to Revision F

Page

• Changed $V_{(ESD)}$ HBM value from ± 2000 V to ± 4000 V in *ESD Ratings table*..... **5**

The datasheet number will be changing.

Device Family	Change From:	Change To:
TLV707, TLV707P	SBVS153E	SBVS153F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TLV707>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TLV707085DQNR	TLV707185DQNT	TLV70729DQNR	TLV707335DQNT
TLV707085DQNT	TLV70718DQNR	TLV70729DQNT	TLV70733DQNR
TLV70710DQNR	TLV70718DQNT	TLV70730DQNR	TLV70733DQNR1
TLV70710DQNT	TLV70725DQNR	TLV70730DQNT	TLV70733DQNT
TLV707115DQNR	TLV70725DQNT	TLV70731DQNR	TLV70734DQNR
TLV707115DQNT	TLV70726DQNR	TLV70731DQNT	TLV70734DQNT
TLV70717DQNR	TLV70726DQNT	TLV70732DQNR	TLV70736DQNR
TLV70717DQNT	TLV707285DQNR	TLV70732DQNT	TLV70736DQNT
TLV707185DQNR	TLV707285DQNT	TLV707335DQNR	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com