



TOSHIBA AMERICA ELECTRONIC COMPONENTS INC.

To: DIGIKEY

April 2015

Please be informed Toshiba has announced discontinuation on the following product(s) in April 2015. Our sales records indicate you have purchased the following product(s) from Toshiba America Electronic Components in the past.

Products

Item No	Discontinued	Last Time Buy	Last Shipment	Substitution	Replacement P/N	Reason
2SC2712S-Y,LF(D)	4/1/2015	6/30/2016	9/30/2016	1	2SC2712-Y,LF(T)	Others
2SC4116SU-GR,LF(D)	4/1/2015	6/30/2016	9/30/2016	1	2SC4116-GR,LF(T)	Others
2SC4116SU-Y,LF(D)	4/1/2015	6/30/2016	9/30/2016	1	2SC4116-Y,LF(T)	Others
TCS10DLU(TE85L,F)	4/1/2015	6/30/2016	9/30/2016	1	TCS30DLU	Discontinuation of Assembly Machine
TCS10DPU(TE85L,F)	4/1/2015	6/30/2016	9/30/2016	1	TCS30DPU	Discontinuation of Assembly Machine
TCS10SPU(TE85L,F)	4/1/2015	6/30/2016	9/30/2016	1	TCS30SPU	Discontinuation of Assembly Machine
TCS20DLR,LF(T)	4/1/2015	6/30/2016	9/30/2016	1	TCS40DLR	Discontinuation of Assembly Machine
TCS20DPR,LF(T)	4/1/2015	6/30/2016	9/30/2016	1	TCS40DPR	Discontinuation of Assembly Machine

Last Time Buy (LTB) Option

Toshiba will support last time buy (LTB) orders received on or before the dates listed above (LTB Date). Last time buy orders for all affected products must be in place in total by LTB Date. Deliveries will be scheduled and advised accordingly after receipt of LTB orders. However, unforeseen circumstances might prevent Toshiba to support partially or fully on LTB orders. If such event occurs, we will notify you of our best support plan as soon as possible. Thank you for your understanding. Should you have any questions, please contact your sales representative.

Best Regards,

Logic Device, Discrete Business Unit
Toshiba America Electronics Components, Inc.

=====

Substitution Level**

0 = No replacement..

1 = Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 = Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 = Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

4 = Other reasons

X34	TCS10SPU(TE85L,F)	38160717	Apr-15	6/30/2016	9/30/2016	1	TOSHIBA	TCS30SPU	Discontinuation of Assembly Machine	ES : Available MP : The end of May, 2015
X34	TCS20DLR,LF(T)	38180922	Apr-15	6/30/2016	9/30/2016	1	TOSHIBA	TCS40DLR	Discontinuation of Assembly Machine	ES : Available MP : The end of May, 2015
X34	TCS20DLR,LF(T)	T1007142	Apr-15	6/30/2016	9/30/2016	1	TOSHIBA	TCS40DLR	Discontinuation of Assembly Machine	ES : Available MP : The end of May, 2015
X34	TCS20DPR,LF(T)	38180923	Apr-15	6/30/2016	9/30/2016	1	TOSHIBA	TCS40DPR	Discontinuation of Assembly Machine	ES : Available MP : The end of May, 2015
X34	TCS20DPR,LF(T)	T1007141	Apr-15	6/30/2016	9/30/2016	1	TOSHIBA	TCS40DPR	Discontinuation of Assembly Machine	ES : Available MP : The end of May, 2015
X34	TTK101MFV-A,L37F(T)	38164058	Apr-15	6/30/2016	9/30/2016	0			Discontinuation of Assembly Machine	
X34	TTK101MFV-B,L37F(T)	38164060	Apr-15	6/30/2016	9/30/2016	0			Discontinuation of Assembly Machine	
X34	TTK501MFV-A,L3F(T)	38164061	Apr-15	6/30/2016	9/30/2016	0			Discontinuation of Assembly Machine	
X34	TTK501MFV-B,L3F(T)	38164064	Apr-15	6/30/2016	9/30/2016	0			Discontinuation of Assembly Machine	
X34	TTK501MFV-B,L3GF(T)	38164072	Apr-15	6/30/2016	9/30/2016	0			Discontinuation of Assembly Machine	