



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: 496

DATE: 04-Jun-2008

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------|---------------------|-------------------------|-----------------|--------------------|------------------------------------|
| Discontinuance | DS2415P | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P+ | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P+T&R | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P-001-711 | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P-001-711/T&R | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P-001-721 | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P-001-721/T&R | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P-W | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P/T&R | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415P/T&R-W | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |
| Discontinuance | DS2415X | N/A | 04-Dec-2008 | 04-Jun-2010 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Jul-2008