


Not Recommended For New Design: Various Package Diodes and Transistors

NRFND.PG31.05.02.2017

05.02.2017

About This Notice:	Effective immediately, below Diode and Transistor part numbers are Not Recommended For New Design due to future discontinuation plans.
Features:	
Effective Date:	Immediate
Affected Parts:	DA2U10100L/DB2U30800L/DB2U30900L/DB2U31400L/DB2U31600L/DB2X20600L DB2X20700L/DB2X41100L/DB2X41400L/DB2X41500L/DA2U10100L/DB2U30800L DB2U30900L/DB2U31400L/DB2U31600L/DB3Y313KEL/DB3Y501KEL/DSCQ00100L BAV99/BAS16/BAV70/2N7002E
Datasheet(s):	See attached Affected Part Numbers list for Datasheet Location on industrial.panasonic.com Japan website.
Notes:	

Panasonic



na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

Relays & Connectors • Capacitors • Circuit Protection • Electromechanical • Sensors
Industrial Automation • Resistors & Inductors • Semiconductors • Wireless Connectivity

Panasonic Industrial Devices Sales Company of America
Two Riverfront Plaza, Newark, NJ 07102