

MACOM Technology Solutions Inc.
100 Chelmsford Street
Lowell, Massachusetts 01851
www.macom.com



January 17, 2023

Digi-Key Corporation
701 Brooks Ave South
Thief River Falls, Minnesota 56701

ATTN: Quality/Purchasing Manager

Subject: Updating pressure seal cover tape

PCN #: PCN-01605

Dear Valued Customer:

The goal of M/A-COM Technology Solutions is to continually deliver high quality products and services that meet our customers' needs. We strive to offer products that are industry leading in terms of performance, delivery, safety and value.

In accordance with these goals, this communication is to inform you that MACOM is updating the cover seal tape for the part numbers listed below. The current 3M 2698 PSA pressure seal cover tape has been obsoleted and recommended replacement is 3M 2668 PSA pressure seal cover tape. This tape is currently used by MACOM on other products.

MAVR-000120-12030P	MADP-011140-14520P
MADP-000910-13050P	MADS-001317-1500AP
MADP-000907-13050P	MADP-000907-14020P
MAVR-000120-14110P	MADP-100907-13050P
MADP-017025-13140P	MADP-000907-1402SP
MADS-001317-1278HP	MADS-001310-1278HP
MADP-001907-13050P	MADP-000300-12690P
MADS-001318-1197HP	MADP-000305-12690P
MAVR-011020-14110P	

You are receiving this notice because you have purchased the above products in the past two years. Details of the change are on the following pages.

Please contact your local sales representative if you have any questions or require additional information.

Sincerely,

Andrew Smethurst
Quality Assurance Manager
MACOM Technology Solutions, Inc.
Tel: +1 (978) 656 2565

E-mail: Andrew.smethurst@macom.com