



Eaton  
114 Old State Road  
Ellisville, MO 63021  
tel: 636-394-2877  
fax: 800-544-2570  
[www.eaton.com/elx](http://www.eaton.com/elx)

**Date: May 1, 2014**  
**To: Eaton's Electronics PowerStor Supercapacitor Customers**  
**Subject: Product Change Notice – Multi-Cell Construction**

Dear Valued Customer:

Effective August 1, 2014, Eaton is implementing construction changes on its PowerStor supercapacitor multi-cell constructions for the specific parts numbers listed in the following pages of this notice.

The change removes a redundant layer of UV epoxy between the rubber seal and the PCB. This change will not affect the parts' form, fit, function, electrical properties, processing requirements or ordering. Any inventory of the specified parts is still saleable product and should not be returned.

If you have any question about this product change, please contact your local Eaton representative. Qualification data is available upon request if required.

Regards,

Jason Lee  
Global Product Manager  
Eaton  
Electronics Division

**Series and Part Number Covered by this Notice:**

**PA Series**

PA-5R0V224-R  
PA-5R0V474-R  
PA-5R0H224-R  
PA-5R0H474-R

**PB Series**

PB-5R0V104-R  
PB-5R0V474-R  
PB-5R0V105-R  
PB-5R0H104-R  
PB-5R0H474-R  
PB-5R0H105-R

**PHB Series**

PHB-5R0V155-R  
PHB-5R0V255-R  
PHB-5R0V305-R  
PHB-5R0V505-R  
PHB-5R0H155-R  
PHB-5R0H255-R  
PHB-5R0H305-R  
PHB-5R0H505-R

**PHV Series**

PHV-5R4V474-R  
PHV-5R4V155-R  
PHV-5R4V255-R  
PHV-5R4V305-R  
PHV-5R4V505-R  
PHV-5R4H474-R  
PHV-5R4H155-R  
PHV-5R4H255-R  
PHV-5R4H305-R  
PHV-5R4H505-R

**PM Series**

PM-5R0V474-R  
PM-5R0V105-R  
PM-5R0V155-R  
PM-5R0V305-R  
PM-5R0H474-R  
PM-5R0H105-R  
PM-5R0H155-R  
PM-5R0H305-R

