



Product Change Notification / SYST-05AVFC311

Date:

06-Jan-2022

Product Category:

Memory

PCN Type:

Document Change

Notification Subject:

Data Sheet - 25AA020A/25LC020A 2-Kbit SPI Bus Serial EEPROM Data Sheet

Affected CPNs:

[SYST-05AVFC311_Affected_CPN_01062022.pdf](#)

[SYST-05AVFC311_Affected_CPN_01062022.csv](#)

Notification Text:

SYST-05AVFC311

Microchip has released a new Product Documents for the 25AA020A/25LC020A 2-Kbit SPI Bus Serial EEPROM Data Sheet of devices. If you are using one of these devices please read the document located at [25AA020A/25LC020A 2-Kbit SPI Bus Serial EEPROM Data Sheet](#).

Notification Status: Final

Description of Change: 1. Added Product Identification System section for Automotive; Updated DFN, PDIP, SOIC, SOT-23, TDFN and TSSOP package drawings; Removed X-rotated TSSOP package offerings; Replaced terminology "Master" and "Slave" with "Host" and "Client", respectively; Replaced "Automotive (E):" designation with "Extended (E):" designation; Reformatted some sections for better readability.

Impacts to Data Sheet: See above details

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 06 January 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[25AA020A/25LC020A 2-Kbit SPI Bus Serial EEPROM Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

25AA020A-I/MS
25AA020A-I/SN
25AA020A-I/P
25AA020A-I/ST
25AA020AT-I/MNY
25AA020AT-I/MS
25AA020AT-I/MC
25AA020AT-I/SN
25AA020AT-I/ST
25AA020AT-I/OT
25LC020A-E/MS
25LC020A-E/SN
25LC020A-E/SN16KVAO
25LC020A-E/P
25LC020A-E/ST
25LC020A-I/MS
25LC020A-I/SN
25LC020A-I/SN16KV03
25LC020A-I/P
25LC020A-I/ST
25LC020A-H/SN
25LC020AT-H/SN
25LC020AT-H/SN16KVAO
25LC020A-H/SN16KVAO
25LC020AT-I/MNY
25LC020AT-I/MS
25LC020AT-I/MC
25LC020AT-I/SN
25LC020AT-I/ST
25LC020AT-I/ST16KV02
25LC020AT-E/MNY
25LC020AT-E/MS
25LC020AT-E/MS16KVAO
25LC020AT-E/MC
25LC020AT-E/MC16KVAO
25LC020AT-E/SN
25LC020AT-E/SN16KV01
25LC020AT-E/SN16KV04
25LC020AT-E/SN16KVAO
25LC020AT-E/ST
25LC020AT-I/OT
25LC020AT-E/OT