

## Product Discontinuance Notification

**Date:** July 14, 2010

**EOL Reference:** EOL503

**Product Reference:** Gen 5.4 Products, 250V or Higher Breakdown

### To Our Valued Customer:

We appreciate your use of International Rectifier (IR) semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our plans to enhance capacity, quality and reliability. We would like to express our sincere appreciation for your cooperation regarding the following changes, and IR will work closely with you to support your requirements during this transition.

### Reason for Product Discontinuance:

Discontinuation of a silicon technology in order to meet contractual obligations.

### Products Affected:

International Rectifier Part Number	International Rectifier Part Number
64-4047PBF	IRFR12N25D
64-4068PBF	IRFR12N25DCPBF
64-4120PBF	IRFR12N25DCTRLP
IRF3000	IRFR12N25DCTRP
IRF3000PBF	IRFR12N25DCTRRP
IRF3000TR	IRFR12N25DPBF
IRF3000TRPBF	IRFR12N25DTR
IRF4000	IRFR12N25DTRL
IRF4000TR	IRFR12N25DTRLP
IRF7453	IRFR12N25DTRPBF
IRF7453PBF	IRFR12N25DTRR
IRF7453TR	IRFR12N25DTRRP
IRF7453TRPBF	IRFR12N25DTRRPB
IRFC12N25DB	IRFU12N25D
IRFC7453B	IRFU12N25DPBF
IRFC12N25DD	

# International Rectifier

233 Kansas St., El Segundo, CA 90245 USA Telephone: +1 310 726 8000 [www.irf.com](http://www.irf.com)

## Effective Dates:

- Last Time Buy: July 13, 2010
- Last Scheduled Shipment: December 31, 2010

## Alternate or Replacement Product:

Contact your local IR representative for suggested replacements.

## Contact Information:

CONTACT	NAME	PHONE	EMAIL
EOL Coordinator	Scott Daniels	+1 951 375 4531	<a href="mailto:sdaniel1@irf.com">sdaniel1@irf.com</a>