



PCN# : P64DAAB
Issue Date : Apr. 20, 2016

Information Only Notification

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

Implementation of change:

Description of Change (From) :

Implementation of PCN P578AAB (HDG4 Technology product produced at the FSC Bucheon 5"/6" Wafer Fabrication Areas).

Description of Change (To) :

Cancellation of PCN P578AAB (HDG4 Technology product produced at the FSC Bucheon 5"/6" and S Portland 8" Wafer Fabrication Areas).

Change will be replaced by PCN# P64CAAB.

Reason for Change:

Fairchild is not moving as many parts as originally planned under PCN 578AAB. Please refer to PCN# P64CAAB. The impacted parts list is being reduced in scope.



Affected Product(s):

FAN7361MX	FAN7362MX	FAN7371MX
FAN7380MX	FAN7380MX_G	FAN7380MX_WS
FAN7382M1X	FAN7382MX	FAN7382MX_G
FAN7382MX_WS	FAN7382N	FAN73832MX
FAN73832MX_T	FAN73833MX	FAN7383MX
FAN7383MX_WS	FAN7384MX	FAN7385MX
FAN7387MX	FAN7387VN	FAN7388MX
FAN7710VN	FAN7711MX	FAN7711N
FAN7842MX	FAN7888MX	FCBB20CH60SF
FCBS0550	FSB32560	FSB50250
FSB50250UD	FSB50250US	FSB50250UTD
FSB50325T	FSB50450	FSB50450S
FSB50450TB2	FSB50450UD	FSB50450US
FSB50550T	FSB50550TB2	FSB50550US
FSB50550UTD	FSB50825TB	FSB50825TB2
FSB50825US	FSB52006S	FSBB15CH60
FSBB15CH60C	FSBB15CH60F	FSBB20CH60
FSBB20CH60C	FSBB20CH60CL	FSBB20CH60CT
FSBB20CH60CTSL	FSBB20CH60C_F139	FSBB20CH60C_SN00327
FSBB20CH60C_T	FSBB20CH60F	FSBB20CH60L
FSBB20CH60SL	FSBB20CH60_T	FSBB30CH60
FSBB30CH60C	FSBB30CH60CM	FSBB30CH60CS
FSBB30CH60CT	FSBB30CH60C_SN00326	FSBB30CH60C_T
FSBB30CH60F	FSBB30CH60FM	FSBF10CH60B
FSBF10CH60BT	FSBF10CH60BTL	FSBF10CH60BTSL
FSBF10CH60BT_T	FSBF15CH60BT	FSBF15CH60BTH
FSBF15CH60BT_T	FSBF15CH60CT	FSBF15CH60CT_T
FSBF5CH60B	FSBF5CH60BS	FSBF5CH60BS_T
FSBS10CH60	FSBS10CH60L	FSBS10CH60L_T
FSBS10CH60SL	FSBS10CH60T	FSBS10CH60_T
FSBS15CH60	FSBS15CH60F	FSBS15CH60L
FSBS15CH60L_T	FSBS15CH60_T	FSBS3CH60
FSBS5CH60	FSBS8CH60T	FSH7101MX
FSSP50CH60S	FSSP50CH60S_T	FTBV1P5SH50U
FTBV1SH25U	FTBV1SH25X	FTBV1SH50U
FTBV1SH50X	FTBVP5SH50U	FTBVP5SH50X
NBC9610	NBC9611	NBC9612
NBC9613	NBC9614	NBC9615
NBC9616		

Appendix A: Changed Products

D

PCN Number : P64DAAB

C

Product	Customer Part Number	BBB	Drawing
FAN7362MX		Y	N
FAN7371MX		Y	N
FAN7380MX		Y	N
FAN7382M1X		Y	N
FAN7382MX		Y	N
FAN73832MX		Y	N
FAN73833MX		Y	N
FAN7383MX		Y	N
FAN7384MX		Y	N
FAN7388MX		Y	N
FAN7711MX		Y	N
FAN7842MX		Y	N
FAN7888MX		Y	N
FSB50550US		Y	N
FSBB15CH60C		Y	N
FSBB20CH60CT		Y	N
FSBB30CH60C		Y	N
FSBB30CH60F		Y	N
FSBF10CH60B		Y	N
FSBF10CH60BTL		Y	N
FSBF15CH60BT		Y	N

Appendix A: Changed Products

D

PCN Number : P64DAAB

C

Product	Customer Part Number	BBB	Drawing
FSB50250		Y	N
FSB50325T		Y	N
FSB50450		Y	N
FSB50450S		Y	N
FSB50450US		Y	N
FSB50550US		Y	N
FSB52006S		Y	N
FSBB15CH60		Y	N
FSBB20CH60		Y	N
FSBB30CH60CT		Y	N
FSBF10CH60B		Y	N
FSBF10CH60BT		Y	N
FSBF5CH60B		Y	N
FSBS3CH60		Y	N